**IS6200 compatible phones** **7/31/2020**

The IS6200 has been tested for compatibility with AT&T CL, CRL, CLP, EL, TL, DL, DLP, BL and VTech CS, DS, IS, LS, SN, VS series home cordless phones. The list below represents models that were tested and confirmed for compatibility with this product.

| VTech cordless phone system | | | | | | |
|---|---|---|---|---|---|---|
| **CS series** | **CS series** | **DS series** | **IS series** | **LS series** | **SN series** | **VS series** |
| CS6919 | CS6949 | DS6421-26 | IS7121 | LS6325-3 | SN1197 | VS112-2 |
| CS6919-15 | CS6949-2 | DS6421-3 | IS7121-2 | LS6325-4 | SN6127 | VS112-3 |
| CS6919-16 | CS6949-3 | DS6472-6 | IS8151-2 | LS6425-2 | SN6187 | VS112-4 |
| CS6919-2 | CS5229 | DS6621-2 | IS8151-3 | LS6425-3 | SN6196 | VS112-27 |
| CS6929 | CS5229-2 | DS662V-1F | IS8151-4 | LS6426-4 | SN6197 | VS112-37 |
| CS6929-15 | CS5329-3 | DS662V-1G | IS8151-5 | LS642V-1F | | VS112-47 |
| CS6929-16 | CS5249 | DS662V-1H | IS81521-5 | LS642V-1G | | VS113-2 |
| CS6929-18 | | DS662V-1J | | LS6475-3 | | VS113-3 |
| CS6929-2 | | DS6670-6C | | LS6476-4 | | VS113-4 |
| CS6929-26 | | DS6671-3 | | | | VS113-5 |
| CS6929-3 | | DS6771-3 | | | | |
| CS5119 | | DS667V-2F | | | | |
| CS5119-13 | | DS667V-2G | | | | |
| CS5119-15 | | DS667V-2H | | | | |
| CS5119-16 | | DS667V-2J | | | | |
| CS5119-17 | | DS6722-3 | | | | |
| CS5119-18 | | DS6672-4 | | | | |
| CS5119-2 | | DS6291 | | | | |
| CS5119-23 | | DS6251 | | | | |
| CS5129 | | DS6251-2 | | | | |
| CS5129-2 | | DS6251-3 | | | | |
| CS5129-26 | | DS6251-4 | | | | |
| CS5129-3 | | DS6161 | | | | |
| CS5129-4 | | | | | | |
| CS5129-5 | | | | | | |
| | | | | | | |

| AT&T cordless phone system | | | | | | | | |
|---|---|---|---|---|---|---|---|---|
| **CL series** | **CL series** | **CRL series** | **CLP series** | **EL series** | **TL series** | **DL series** | **DLP series** | **BL series** |
| CL81201 | CL83201 | CRL32102 | CLP99383 | EL52345 | TL16013 | DL72119 | DLP73210 | BL102-2 |
| CL81301 | CL83301 | CRL32202 | CLP99483 | EL52365 | TL86103 | DL72219 | DLP73410 | BL102-3 |
| CL81211 | CL83451 | CRL81212 | CLP99453 | EL52145 | TL86109 | DL72319 | | BL102-4 |
| CL81214 | CL83143 | CRL82212 | CLP99553 | EL52245 | TL92271 | DL72419 | | |
| CL82101 | CL83114 | CRL82312 | CLP99573 | EL52106 | TL92371 | DL72210 | | |
| CL82201 | CL83214 | | CLP99386 | EL52306 | TL96271 | DL72310 | | |
| CL82301 | CL83314 | | CLP99486 | EL52119 | TL92273 | | | |
| CL82351 | CL83364 | | CLP99586 | EL52219 | TL96273 | | | |
| CL82401 | CL83414 | | CLP99387 | EL52319 | TL96423 | | | |
| CL82451 | CL83464 | | CLP99487 | EL52419 | TL96477 | | | |
| CL82501 | CL83215 | | CLP99587 | | TL96487 | | | |
| CL82215 | CL83315 | | | | TL96497 | | | |
| CL82315 | CL83415 | | | | TL96547 | | | |
| CL82415 | CL83203 | | | | | | | |
| CL82465 | CL83213 | | | | | | | |
| CL82515 | CL83413 | | | | | | | |
| CL82311 | CL83463 | | | | | | | |
| CL82321 | CL83484 | | | | | | | |
| CL82213 | CL83207 | | | | | | | |
| CL82313 | CL83407 | | | | | | | |
| CL82413 | CL83519 | | | | | | | |
| CL82513 | CL84102 | | | | | | | |
| CL82463 | CL84202 | | | | | | | |
| CL82214 | CL84252 | | | | | | | |
| CL82314 | CL84352 | | | | | | | |
| CL82464 | CL84215 | | | | | | | |
| CL82207 | CL84365 | | | | | | | |
| CL82257 | CL84115 | | | | | | | |
| CL82307 | CL84107 | | | | | | | |
| CL82357 | CL84207 | | | | | | | |
| CL82407 | CL82219 | | | | | | | |
| CL82507 | CL82229 | | | | | | | |
| CL82547 | CL82319 | | | | | | | |
| CL82557 | CL82419 | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |